


DIFFERENT STYLE AND DETAILING OF THE NEWER EXTENSIONS IN COMPARISON WITH THE ORIGINAL BUILDING





LEVEL ACCESS TO GARDEN FROM BEDROOMS UNFEASIBLE WHICH MEANS RESIDENTS WOULD NOT BE ABLE TO ACCESS EXTERNAL SPACES INDEPENDENTLY



STEPPED ACCESS TO THE GARDEN FROM COMMUNAL ROOMS WOULD REQUIRE EXTENSIVE RAMPS TO OVERCOME LEVEL DIFFERENCE




MEANDERING ROUTE THROUGH THE SETTING, LACK OF CONNECTIVITY INSIDE-OUT





STEPS AS PART OF THE CORRIDORS



INTERNAL CHANGES OF LEVELS WITHIN AREAS POTENTIALLY ACCESSIBLE TO RESIDENTS, VARIETY OF CORRIDOR WIDTHS AND LACK OF PASSING PLACES



LOW HEADROOM - ACCOMMODATION WILL SUFFER FROM REDUCED HEADROOM ONCE NEW SERVICES INSTALLED






NO SUITABLE ACCESS TO UTILIZE REAR GARDEN





THE MAIN ENTRANCE





THE COURTYARD





THE GLAZED LINK









THE FRONT DOOR DOOR AND WINDOW DETAILING THE GLAZED LINK





THE UPPER LEVEL TERRACE





THE REAR GARDEN

